

2018-68 | BMW 2 SERIES

216D SPORT ACTIVE TOURER | Diesel | Manual |



<https://www.tyrrellautomotive.com>
01280 821886



£10,595

Mileage **35,870 miles**

Fuel **Diesel**

Owners **2**

Engine **1.5 litre**

Transmission **Manual**

Gears **6**

SPECIFICATIONS

Twin horns	Cruise control with brake assist	Heated door mirrors
Central locking switches for door, fuel filler cap and luggage compartment	Non-smoker package	Drive performance control with ECO PRO comfort + sport mode
High gloss black interior trim with pearl chrome finish	Thatcham 1 alarm system with remote control and engine immobiliser	DAB Digital radio
Reduced rolling resistance tyres	Manual 40	Front ventilated disc brakes
On board computer - average speed+fuel consumption, service interval, clock/date, odometer/trip meter, outside temperature display and ice warning	Shark fin antenna	Front armrest
BMW Navigation pack - 2 Series	Incorrect fuelling protection	Contrast stitching on instrument panel
Start/stop button with Comfort Go keyless engine start and auto Start/stop deactivation button	6 speakers	17" Burnished double spoke alloy wheels finished in orbit grey - style 549
Crash Sensor - activates hazard/interior lighting + unlocks doors	BMW remote services	High level third brake light
Three spoke sport leather steering wheel	Extended storage pack - 2 Series Active/Gran Tourer	VALVETRONIC engine management

TECHNICAL

Performance	
0-100 kmh (62 mph)	11.1 s
Top speed	121 mph
Emissions Ice	
CO ₂ (g/km)	104 (g/km)
Fuel Consumption Ice	
MPG (combined)	60.1 mpg
L/100km (combined)	4.7 l/100km
MPG (combined)	70.6 mpg
MPG (extra urban)	78.5 mpg
MPG (urban)	62.8 mpg
Capacities	
Boot (seats up)	468 litres
Boot (seats down)	1510 litres
Fuel tank	51 litres

....MORE.... For the full details please call us or scan the QR code above

01280 821886

chris@tyrrellautomotive.com

Tyrrell Automotive Limited Vitalograph Business Park Maids Moreton Bucks MK18 1SW

Whilst every effort has been made to ensure the accuracy of the vehicle specification, some inaccuracies may occasionally occur. It is important that you do not rely solely on this information, but check with a member of the sales staff about any features which may affect your decision to buy the car.